







F series (GOBLET)

Gauge pattern		Type	Gauge size(mm) Length Width		Backing size(mm) Length Width		Resist- ance Ω
●0° /90° 2-axis Stacked type							
	 FCAB-1	 FCAB-2					
	 FCAB-3	 FCAB-5					
	 FCAB-6	 FCAB-10					
●350Ω 0° /90° 2-axis Stacked type							
	 FCAB-1-350	 FCAB-2-350					
	 FCAB-2-350	 FCAB-5-350					
FCAB-1-350  (x 3)							
●0° /45° /90° 3-axis Stacked type							
	 FRAB-1	 FRAB-2					
	 FRAB-3	 FRAB-5					
	 FRAB-6	 FRAB-10					
●350Ω 0° /45° /90° 3-axis Stacked type							
	 FRAB-1-350	 FRAB-2-350					
	 FRAB-3-350	 FRAB-5-350					
FRAB-1-350  (x 3)							
Minimum order quantity is 10 strain gauges.							

Minimum order quantity is 10 strain gauges.